FO" COATINGS, RESINS AND RELATED! TERIALS

DATE OF PREP. JULY 1982

(Approved by U.S. Department of Labor "Essentially Similar" to Form OSHA-20)

JUL 12 1982

Section I

MANUFACTURER'S NAME

BOSTIK WEST, DIVISION OF EMHART CORPORATION

20846 S. NORMANDIE AVE. STREET ADDRESS CITY, STATE, AND ZIP CODE

TORRANCE, CA.

90502

EMERGENCYTELEPHONE NO. (213) 320-6800

PRODUCT CLASS AMINE CURING SOLUTION

(DMS 1738-17875)

TRADE NAME BOSTIK MANUFACTURERS CODE IDENTIFICATION

CA-131

CURING SOLUTION FOR 463-3-40TRS

MIX RATIO: 706 GMS. 463-3-40TRS (BASE) TO

315 GMS. CA-131

Section		JUS I		

CA-131 (*EPOXY CURING SOLUTION)	CAS NO.	PERCENT (Wt.)	TLV PPM	mg/M³	LEL	VAPOR PRESSURE
BUTYL CELLOSOLVE	111-76-2	10-15	50		1.1	1
METHYL ETHYL KETONE	78-93-3	25-30	200		1.8	70
NORMAL BUTYL ACETATE	123-86-4	25-30	150		1.7	8
NORMAL BUTYL ALCOHOL	71-36-3	25-30	100		1.7	4
TOLUENE	108-88-3	1–5	200		1.2	22
*CA-131 MAY ALSO CONTAIN A MINOR AMOUNT OF DIETHYLENE TRIAMINE					1.4	إ 1.0
(DETA)	111–40–0		1.0		1.4	7. .0
and the state of			(ACGIH, TWA)			

Section III - PHYSICAL DATA

BOILING RANGE 1760-	340 ⁰ F		VAPOR DENSITY X	HEAVIERI	LIGHTER, THAN AIR
EVAPORATION RATE	FASTER X SLOWE	ER, THAN ETHER PERC BY VO	ENT VOLATILE DLUME 95	WEIGHT PER GALLON 7.1LI	3S.

•		Section IV — FIR	E AND EXPLOSIO	N HAZARD DATA	
DOT CATEGORY	RED LABEL,	FLAMMABLE	(MIN.) Flash Point	23°F, TAG CLOSED CUP	LEL 1.1
EXTINGUISHING M	IEDIA				•
		Exclude air	-Use foam, CO ₂ ,	steam, water fog, water.	
androne of the second second		dry chemica	ıls. Do not use	water.	
UNUSUAL FIRE AN	ID EXPLOSION HAZ	ARDS			
		Vapor forms		ure with air between	1
		upper and l	ower explosion	limits.	The second second
SPECIAL FIRE FIG	•				

Do not use water, exclude air, use water spray to cool fire exposed surfaces and to protect personnel.

→ction V — HEALTH HAZARD E A
THRESHOLD LIMIT VALUE See Section II
EFFECTS OF OVEREXPOSURE Headache, nausea, dizziness. Breathing vapor will be irritating to nose, throat, and eyes.
是一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个
EMERGENCY AND FIRST AID PROCEDURES: Skin Exposure: Wash affected area with soap and water. Eye Exposure: Flush with water for at least 15 minutes, consult physician. Ingestion: Consult physician immediately. Inhalation: Remove victim to fresh air, consult physician.
Section VI — REACTIVITY DATA
STABILITY UNSTABLE XX STABLE CONDITIONS TO AVOID Storage at high temperatures. INCOMPATABILITY (Materials to avoid) Strong oxidizing agents. Sparks & open flame.
HAZARDOUS DECOMPOSITION PRODUCTS On combustion CO, CO, Aldehydes and other organics, oxides of nitrogen.
HAZARDOUS POLYMERIZATION MAY OCCUR WILL NOT OCCUR CONDITIONS TO AVOID
Section VII — SPILL OR LEAK PROCEDURES
STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED: Eliminate sources of ignition and clear fume:
from area. Prevent liquied from entering sewers, water sources, or low areas. Keep unnecessary personnel away. Shut off source, if possible to do so without wastedisposal method hazard. Contain spilled liquid with sawdust, sand or oil absorbing compound. Wash area with detergent & water. Consult disposal expert and ensure conformity with local regulations.
Section VIII — SPECIAL PROTECTION INFORMATION
Section VIII — SPECIAL PROTECTION INFORMATION RESPIRATORY PROTECTION: Use approved respiratory protection such as an air-supplied masl if used in non ventilated area. Mechanical: Explosion-proof ventilation equipment. No smoking or open lights.
RESPIRATORY PROTECTION: Use approved respiratory protection such as an air-supplied mass if used in non ventilated area. Mechanical: Explosion-proof ventilation equipment. No smoking or open lights.
RESPIRATORY PROTECTION: Use approved respiratory protection such as an air-supplied mass if used in non ventilated area. Mechanical: Explosion-proof ventilation equipment. No smoking or open lights.
RESPIRATORY PROTECTION: Use approved respiratory protection such as an air-supplied mass if used in non ventilated area. Mechanical: Explosion-proof ventilation equipment. No smoking or open lights. VENTILATION: Face velosity 60fpm in confined area.
RESPIRATORY PROTECTION: Use approved respiratory protection such as an air-supplied mass if used in non ventilated area. Mechanical: Explosion-proof ventilation equipment. No smoking or open lights. VENTILATION: Face velosity 60fpm in confined area. PROTECTIVE GLOVES Chemically resistant gloves. EYE PROTECTION Chemical splash goggles or face shield.
RESPIRATORY PROTECTION: Use approved respiratory protection such as an air-supplied mass if used in non ventilated area. Mechanical: Explosion-proof ventilation equipment. No smoking or open lights. VENTILATION: Face velosity 60fpm in confined area. PROTECTIVE GLOVES Chemically resistant gloves.
RESPIRATORY PROTECTION: Use approved respiratory protection such as an air-supplied masifused in non ventilated area. Mechanical: Explosion-proof ventilation equipment. No smoking or open lights. VENTILATION: Face velosity 60fpm in confined area. PROTECTIVE GLOVES Chemically resistant gloves. EYE PROTECTION Chemical splash goggles or face shield. OTHER PROTECTIVE EQUIPMENT Eye bath & Safety shower. Section IX — SPECIAL PRECAUTIONS
RESPIRATORY PROTECTION: Use approved respiratory protection such as an air-supplied mash if used in non ventilated area. Mechanical: Explosion-proof ventilation equipment. No smoking or open lights. VENTILATION: Face velosity 60fpm in confined area. PROTECTIVE GLOVES Chemically resistant gloves. EYE PROTECTION Chemical splash goggles or face shield. OTHER PROTECTIVE EQUIPMENT Eye bath & Safety shower.
RESPIRATORY PROTECTION: Use approved respiratory protection such as an air-supplied mass if used in non ventilated area. Mechanical: Explosion-proof ventilation equipment. No smoking or open lights. VENTILATION: Face velosity 60fpm in confined area. PROTECTIVE GLOVES Chemically resistant gloves. EYE PROTECTION Chemical splash goggles or face shield. OTHER PROTECTIVE EQUIPMENT Eye bath & Safety shower. Section IX — SPECIAL PRECAUTIONS PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING: Keep containers closed when not in use. Do Not handle or store near flame, heat or strong oxidants. Adequate ventilation
RESPIRATIONY PROTECTION: Use approved respiratory protection such as an air-supplied mass if used in non ventilated area. Mechanical: Explosion-proof ventilation equipment. No smoking or open lights. VENTILATION: Face velosity 60fpm in confined area. PROTECTIVE GLOVES Chemically resistant gloves. EYE PROTECTION Chemical splash goggles or face shield. OTHER PROTECTIVE EQUIPMENT Eye bath & Safety shower. Section IX — SPECIAL PRECAUTIONS PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING: Keep containers closed when not in use. Do Not handle or store near flame, heat or strong oxidants. Adequate ventilation required. Containers of this product may be hazardous when emptied -these other precautions containers retain product residues (vapor, liquid, etc.). All handling equipment should be electrically grounded. Treat as a very
RESPIRATORY PROTECTION: Use approved respiratory protection such as an air-supplied mast if used in non ventilated area. Mechanical: Explosion-proof ventilation equipment. No smoking or open lights. VENTILATION: Face velosity 60fpm in confined area. PROTECTIVE GLOVES Chemically resistant gloves. EYE PROTECTIVE GLOVES Chemically resistant gloves. EYE PROTECTIVE COUPMENT Eye bath & Safety shower. Section IX — SPECIAL PRECAUTIONS PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING: Keep containers closed when not in use in the second and the containers of this product may be hazardous when emptied - these other precautions containers retain product residues (vapor, liquid, etc.). All handling equipment should be electrically grounded. Treat as a very flammable liquid.
RESPIRATORY PROTECTION: Use approved respiratory protection such as an air-supplied mass if used in non ventilated area. Mechanical: Explosion-proof ventilation equipment. No smoking or open lights. VENTILATION: Face velosity 60fpm in confined area. PROTECTIVE GLOVES Chemically resistant gloves. EYE PROTECTION Chemical splash goggles or face shield. OTHER PROTECTIVE EQUIPMENT Eye bath & Safety shower. Section IX — SPECIAL PRECAUTIONS PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING: Keep containers closed when not in use too handle or store near flame, heat or strong oxidants. Adequate ventilation required. Containers of this product may be hazardous when emptied - these other precautions containers retain product residues (vapor, liquid, etc.). All handling equipment should be electrically grounded. Treat as a very flammable liquid.